



March 24, 2026

Bloomfield Homes Homeowner

Re: Electrolux Group Safety Recall Notice – Frigidaire Gas Ranges.

Dear Homeowner:

Electrolux Group (“Electrolux”) recently announced a voluntary product recall regarding certain Frigidaire gas ranges due to an issue causing delayed ignition of oven bake burners with the potential for burn risk. More specific information regarding the recall, including the models and serial number ranges affected, can be found on the Electrolux Safety Recall Notice dated March 19, 2026 and attached hereto. You can also find information regarding the recall at [www.GasOvenBurnerRecall.com](http://www.GasOvenBurnerRecall.com). If your Frigidaire gas range is on the affected list, you should stop using the oven until service has been performed and the remedy addressing the recall is completed. You can continue to use the cooktop burners.

Electrolux is offering free in-home service to professionally evaluate and install a new oven bake burner. You can schedule service to receive installation of a new oven bake burner, free of charge, at [www.GasOvenBurnerRecall.com](http://www.GasOvenBurnerRecall.com). It is important that you follow the “What You Should Do” recommendations on the attached Safety Recall Notice.

Thank you for your immediate attention to this notification.

Bloomfield Homes, LP



Safety Recall Notice

March 19, 2026

To our valued consumers:

Electrolux Group, in cooperation with the U.S. Consumer Product Safety Commission (CPSC), has announced a voluntary recall of certain Frigidaire gas ranges due to an issue causing delayed ignition of oven bake burners with the potential for burn risk.

Our records indicate that you may have purchased a recalled model from one of our retail partners. The ranges were sold in white, black and stainless steel colors. The serial number is located in the drawer beneath the oven. The following model and serial numbers are included in this recall:

Models	Serial Range
FCFG3083AS, FCRG3083AD, FCRG3083AS, GCFG3060BD, GCFG3060BF, GCFG3070BF, GCRG3060BD, GCRG3060BF, PCFG3080AF, FCFG3062AB, FCFG3062AS, FCFG3062AW, FCRG3051BB, FCRG3051BS, FCRG3051BW, FCRG3052BB, FCRG3052BS, FCRG3052BW, FCRG3062AB, FCRG3062AS, FCRG3062AW, FCRG306LAF, GCFG3059BF	VF52200000 through VF54399999

Electrolux Group is conducting free in-home service to provide consumers with professional installation of a new oven bake burner.

**What You Should Do:**

1. Check [www.GasOvenBurnerRecall.com](http://www.GasOvenBurnerRecall.com) to see if *both* your model and serial number are on the affected range list. Both numbers can be found in the drawer beneath the oven.
2. If it is on the affected list, consumers should stop using the oven until service has been performed and the remedy addressing the recall is completed. The cooktop burners can continue to be used.
3. If it is on the affected list, consumers can schedule service to receive professional installation of a new oven bake burner, free of charge, at [www.GasOvenBurnerRecall.com](http://www.GasOvenBurnerRecall.com).

The safety of our consumers is a very serious matter and not something that Electrolux Group takes lightly. Thank you for your ongoing partnership and understanding as we strive to continuously improve. We appreciate your business.

Sincerely,

Chad Strickland  
Product Safety Director  
Electrolux Group North America